

Junções


Unions

Manchons union

Enlaces 3 piezas



04 07 4117 000



d	G	D	D1	l1	l2	Z1	Z2	Gr	Quant	Nº Código
1/2"	40x10	46	28	26	20	10	3	39	B 60	04 07 4114 012
3/4"	47x10	56	36	28	23	10	3	61	B 40	04 07 4114 034
1"	53x8	67	42	30	26	10	3	90	B 20	04 07 4114 100
1 1/4"	66x8	82	52	41	31	13	3	153	C 60	04 07 4114 114
1 1/2"	74x8	88	63	45	35	14	3	198	C 45	04 07 4114 150
2"	90x8	106	77	52	42	14	3	328	C 30	04 07 4114 200

Junções


Unions

Manchons union

Enlaces 3 piezas



04 07 4117 000



Union nuts

d	G	I	D	Gr	Quant	Nº Código
"1/2	40x10	22	46	16		04 01 4118 012
"3/4	47x10	26	56	26		04 01 4118 034
1"	53x8	28	67	42		04 01 4118 100
1"1/4	66x8	30	82	62		04 01 4118 114
1"1/2	74x8	31	88	68		04 01 4118 150
2"	90x8	38	106	113		04 01 4118 200

Junções


Unions

Manchons union

Enlaces 3 piezas



04 07 4117 000



Union ends

d	A	D	I	Z	Gr	Quant	Nº Código
1/2	36	28	20	3	8		04 07 4116 012
3/4	43	36	23	3	13		04 07 4116 034
1"	50	42	26	3	18		04 07 4116 100
1 1/4"	63	52	31	3	28		04 07 4116 114
1 1/2"	69	63	35	3	48		04 07 4116 150
2"	83	77	42	3	83		04 07 4116 200

Junções


Unions

Manchons union

Enlaces 3 piezas



04 07 4117 000



Union bushes

d	G	I	Z	E	F	H	D	Gr	Quant	Nº Código
1/2	40x10	26	10	28.4	4.3	2.5	28	14		04 07 4117 012
3/4	47x10	28	10	35.5	4.8	2.5	36	21		04 07 4117 034
1"	53x8	30	10	39.6	4.6	2.5	42	29		04 07 4117 100
1 1/4	66x8	41	13	51.8	7	4	52	52		04 07 4117 114
1 1/2	74x8	45	14	57	7	4	63	77		04 07 4117 150
2"	90x8	52	14	70	7	4	77	126		04 07 4117 200