

Uniões de redução


Reduced union

Manchons de réduction

Manguitos reducidos



20 41 2007 000



d	d1	A	B	C	D	E	F	G	H	Gr	Quant	Nº Código
20	16	100	35	39	39	46	22	12	7	71		20 41 2007 003
25	16	101	35	41	39	52	27	13	10	85		20 41 2007 004
25	20	106	39	41	46	52	27	13	10	98		20 41 2007 005
32	20	120	39	52	46	64	34	19	12	138		20 41 2007 009
32	25	125	41	52	52	64	34	19	12	142		20 41 2007 010
40	25	130	41	61	52	7	41	23	13	207	100	20 41 2007 014
40	32	140	52	61	64	78	41	23	13	240	85	20 41 2007 015
50	25	147	41	68	52	92	51	31	13	260	60	20 41 2007 018
50	32	162	52	68	64	92	51	31	13	307	60	20 41 2007 019
50	40	163	61	68	78	92	51	31	13	367	60	20 41 2007 020
63	32	169	52	64	83	109	64	39	22	460	40	20 41 2007 023
63	50	193	61	78	83	109	64	39	22	560	30	20 41 2007 025
75	63	232	83	109	107	132	76	40	23	882	18	20 41 2007 030
90	63	253	83	109	131	151	94	57	31	1130	12	20 41 2007 034

Uniões de redução


Reduced union

Manchons de réduction

Manguitos reducidos



20 41 2007 000



(continuação)

d	d1	A	B	C	D	E	F	G	H	Gr	Quant	Nº Código
90	75	265	107	132	131	151	94	57	31	1270	12	20 41 2007 035
110	75	348	107	132	166	175	112	57	36	2210	8	20 41 2007 039
110	90	353	131	151	166	175	112	57	36	2250	8	20 41 2007 040